# Utah Department of Environmental Quality Division of Drinking Water

# Public Water System Inventory Report

Run Date: 08/04/2011 12:34 pm

PWS ID: UTAH22001 Name: CLUFF WARD PIPELINE CO

Legal Contact CLUFF WARD PIPELINE CO Rating: Approved

DOUGLAS VERAN MOORE Rating Date: 03/11/1993

Address: 501 E CHALK CRK RD Activity Status: Active

COALVILLE, UT 84017

Phone Number: City Served (Area):

County: SUMMIT COUNTY

Gal/Day Gal/Min

System Type: Community

Last Inv Update: 05/25/2010

Activity Status Cd: Active

Last Snty Srv Dt: 10/21/2009

Total Dsgn Cap:

Surveyor: MARK E HANSEN

Total Emerg Cap:

Oper Period: 1/1 to 12/31

**Contacts** 

Contact	t Phone Numbers								
Type	Name	Title	Office	Emergency	Email Address				
AC	MOORE, DOUGLAS VERAN		435-336-5981	435-336-5864	dvmoore2264@hotmail.com				

#### Service Connections

Connection			Number	
Туре	Meter Type Code	Meter Size	Connections	<b>S</b>
Residential	Metered	0	74	
			74 <b>1</b>	− 「otal Svc Connections

## Storage

Total Storage: 92,000 GAL Number of Units: 2 Adequate Capacity: YES

				Constr	Overflow	Activity		
No.	Name	Type	Effective Volume	Matrl	Elev	Status	Press'd	
ST001	STORAGE FACILITY ST001	Ground	80,000 GAL	Concrete		Α	NO	
ST002	SAGE HOLLOW STORAGE	Ground	12,000 GAL	Concrete		Α	NO	

### **Treatment Plants**

No.	Plant Name	Approved Design Capacity (gal/day)	Status	Process
TP001	WILDE (PASTURE) CHLORINATOR		Α	

## **Distribution System**

Pump Type	Total Dy	n Head	Pressure	Cross	Auhority
	ft H2O	P.S.I.	Adequate	Connection	Statement
•			No		

#### Sources

No.	Source Name	Activity Status	Source Type	Well Dia.	Safe Yield *	Pump Capacity	Location Data On File	Water Type	Availability	Period of Operation	Grnd Wtr Indicator
WS001	WILDE (PASTURE) SPRING	Active	SP				Yes	GW	Permanent	1/1 to 12/31	
WS002	SAGE HOLLOW SPRING	Active	SP				Yes	GW	Permanent	1/1 to 12/31	
WS003	WILDE WELL	Inactive	WL	6	30 GPM		Yes	GW	Other		

<sup>\*</sup>Reports measured flow for wells, approved design capacity for all other sources.